## Machinery.

ENGINEERING EDITION.

Index to Vol. X.

September, 1903, to August, 1904.

1904.

THE INDUSTRIAL PRESS.

66 WEST BROADWAY.

NEW YORK.

## Index to Volume X.

Alloys of High Tensile		Curtis Steam Turbine and Its	The Useful Elephant 654	Journal, An Air Lubricated.	
Strength. Herbert E.	215	Manufacture, The 1 Cutter Working on a New	"Thermit," Lecture Upon. 183 To Europe in Sixty Hours 655	Arthur W. Cole	468
Alloys Suitable for Bearing	010	Principle, A Milling 354 Cutting Fractional Screw	Turbine Developments,	Jump Drill or Trepan, Ex- traordinary Shaft Sinking	
Purposes, A Study of Alloys, Zinc Aluminum	514	Threads. Fred H. Colvin. 143	Turbine Developments, Other	with the	464
Alternating-current Motors	014	Inteaus. Freu II. Colvin. 143	Pays 418	Kaup, W. J.:	
for Railway Work—American Developments. Wm.		Death of Robert H. Thurs-		Metal Coloring Kleinhans, Frank B.	179
Baxter, Jr	304	ton, Sudden 134	"Factor of Safety" 181 Fair of '46, Anecdotes of	Deep Drilling	244
American Blower Co.'s New		Deep Drilling. Frank B. Kleinhans	the 40 Fairfield, Howard P.:	Use of Diagrams and Ta-	
	14	Design of Punch and Riveter	Spindle Construction (1). 523	bles for the Solution of Problems in Gearing	357
Meeting	227	Frames. John S. Myers 127 Design, Notes on. C. F.	(2)		
cago, May 31	417	Blake:	Field, Herbert E.: Alloys of High Tensile	Latent Heat Question, The. Lathe, Hydraulic-Feed 14-	4.53
A. S. M. E., Twenty-fourth	071	(1) Machinery Shafting. 362 (2) Machinery Shafting,	Strength	inch Boring Lathe, Koehler's Profile, Rob-	335
Automobiling, Early	402	(concluded) 397	Fireproof Paints, Value of 509 Fitch, Charles H.:	ert Grimshaw	528
		Designation of Standard Ma- chine Parts 215	Accurate Machine Descrip-	Lathe Spindles, Talk on. F.	
Baltic, The New White Star Steamer	662	Die Head, Adjustable, and	Flanders, Ralph E.:	Emerson Lathe Work, Estimating	480
Bauer Propeller-blade Shap-		Method for Making Threaders for Use in same. Jos.	Camming, Directions for, the B. & Sharpe Auto-	Time for, Henry Hess Le Blond Automatic Index-	449
Baxter, Wm., Jr.:		M. Stabel 207	matic Screw Machine 6	Plate Drilling Machine	346
Variable Speed Motors, 395, 452, 512, 573, 6	090	Die Making, Notes on. Frank E. Shailor 649	Making Master Cams 603	Le Blond Machine Tool Co.'s	
Beams and Planes Severally	000	Differentiation of Engineer-	Flexure Simplified. John S. Myers	Shop, R. K Lee, G. E.	403
Supported and Eccentri-		ing, The	Floorplate and Concrete	Counterbalancing Locomo-	
cally Loaded, Problems in. C. F. Blake  Beams, Flexure of (Flexure	571	the Shop 20	Foundation, Long 651 Fore River Ship and Engine	tives Leonard, W. S.	909
Beams, Flexure of (Flexure Simplified)	104	Drilling Machine, Le Blond Automatic Index Plate 346	Company's Plant, Improve-	Leonard, W. S. Some Practical Points in	415
Bell, A. R.:	194	Drives for High-Speed Cut-	ments at the. E. L. C 462 Forming Tools, Straight and	Machine Design Locomotive, Centenary of	410
Centenary of the Locomo-	0==	ting Tools, Comments on. C. E. Coolidge 507	Circular, Jos. M. Stabel. 515	the, 1803-1904, A. R. Bell	457
tive, 1803-1904 2 Early Steam Engines	509	Dynamos, Humming of 666	Foundry and Pattern Departments of the B. F. Sturte-	Locomotives. Counterbalanc- ing. G. E. Lee	365
Betts Machine Co., The Re- constructed Shop of the	00	Eccentrolinead, The. M. S.	vant Co 121	Machine Description, Accu-	
Bicycle Two-Speed Gear, The	22	Smith	Gardner, F. N.:	rate. Charles H. Fitch	28
Columbia	531	Electricity from Fuel, The Reid Process of Produc-	A Talk on the Disk Grind-	Machine Besigns, Some Prac- tical Points In. W. S.	
Table for Computing the		ing 254	Gas Distribution by Gas	Leonard	415
Cost of Castings 5	536	Emerson, F.: Talk on Lathe Spindles 485	Power, High Pressure 367	Leonard  Machine Shop Equipment.  Oscar E. Perrigo:	
Blake, C. F.: Notes on Design362-3	397	Engine with Corliss Gear,	Gas Turbine, The 17 Gear, The Columbia Bicycle	(1)	11
Problems in Beams and Planes Severally Sup-		A Marine	Two-Speed 531	(2) Equipment of Tool Room and Store Room.	72
ported and Eccentrically		cation of the Advance of. 509	Gear Cutter, Old: History John Steptoe Shaper Co 217	(3) Plans for the Draw-	
Loaded	572	Engineering, The Differentia-	Gearing, Use of Diagrams and Tables for the Solu-	ing Room and its Equip- ment	111
Blowing Engines with Me- chanically Operated Pis-		Engines, Early Steam 509	tion of Problems in. Frank	(4) Equipment of the Pat-	
ton Valves for Air Cylin-	10=	Estimating Time for Lathe Work. Henry Hess 449	B. Kleinhans 357 Gears, Spiral. C. E. Cool-	tern Shop and Pattern Storage Room	171
Boiler Bracing. Charles L.	191	Explosions, Compressed Air. 402	idge 30	(5) Equipment of the Iron	
Boiler Bracing. Charles L. Hubbard (1)	18	Exposition, Question of Power at the St. Louis 352	Gordon, J. R.:	Foundry	240
(2) Calculations for Through Stays	82	Exposition, The Louisiana	Some Tools Used in the Manufacture of Globe	Forge Shop	293
Through Stays		Purchase	Valves 427	(7) Shop Transportation	
Worm-driven Boring Mill, The Poole	25	Editorial:	Gradenwitz, Dr. Alfred: The Single-phase Motor in	Equipment	
worm-driven	81	Alcohol for Industrial Pur-	Europe 305	Machine Tools What are the	409
Bridge, New Williamsburg, Opened to Pedestrians,		Allis-Chalmers Co., New	Use of Magnets in Con- nection with Cranes 590	New, to be? Prof. John	0.50
Dec. 19	228	Ventures of the 419 A New Old Engine 16	Electrically-driven Port-	E. Sweet	$\frac{253}{668}$
Brown, Walter: High Speed Tool Steels 5	534	Are the Claims for Educa-	able Tools 652 Grimshaw, Robert:	ment Machine Tools, What are the New, to be? Prof. John E. Sweet Machinists' Den. A. Magnets in Connection With	
Bullock Electric Mfg. Co.,	283	tion Made Good? 76 Are We Eager to Learn? 472	Koehler's Profile Lathe 528	Cranes, The Use of. Dr. Alfred Gradenwitz	590
		Asked to Ante-up 654	Grinder, A Talk on the Disk. F. N. Gardner 547	Markham, E. R.	
Cams, Making Master	603	Automatic Sprinklers on Shipboard 655	Gun, Breech Mechanism of the 16-inch Coast Defense 176	Speeds and Feeds	$\frac{105}{289}$
Camming the Brown & Sharpe Automatic Screw		Automobile, The Danger-	the 16-men Coast Defense 176	340, 412, 481, 519, 592,	663
Machine, Directions for. Ralph E. Flanders	6	Compressed Air and Ma-	Hamilton Corliss Engine Works, The New 231	High Speed Steel  Measuring External Thread	300
Card Index in the Drafting	U	chine Tools 530	Hardening Cast Iron, Pro-	mameters. Joseph M.	248
Room, The	152	Cunard Company Leads off 473 Data, Suppressed 472	cess for	Machanical Torms . A Criti-	
ening Castings, Table for Comput-	578	Electricity as a Motive	Plant, Unique 21	Metal Coloring. W. J. Kaup Microphotography. W. H.	495
ing the Cost of. W. W.		Power for Machine Shops 16 Engineers, Examination for	Hess, Henry: Estimating Time for Lathe	Microphotography. W. J. Kaup Wi. H.	110
Birnstock	536	Stationary 182 Genius, Mis-Directed In-	Work	Sargent Milling Cutter Working on	485
1803-1904. A. R. Bell	457	ventive 594	Comments on Drives for.	a New Principle, A	354
Chain, Notable Installation	450	Government Experiments. 76	C. E. Coolidge 507	Motor, Alternating-Current Railway	
1803-1904. A. R. Bell 4 Chain, Notable Installation of the Renold Silent 4 Cincinnati Shaper Co., New	196	Haswell, Chas H 594 Improving the Steam En-	High Speed Steel 17 High Speed Steel E. R.	Motor Drives for Hartness Flat-turret Lathe	1-0
Shop of the	116	gine	High Speed Steel. E. R. Markham	Flat-turret Lathe Motor, The Single-phase, in	316
Friction	100	Inventions and What Con-	ter Brown	Europe. Dr. Alfred Grad-	00
Cole, Arthur W.:		stitutes Abandonment 594 Is this General English	High-Speed Tool Steel Tests 300	Motors, Alternating-current	305
An Air Lubricated Jour- nal	168	Practice? 900	Hollow Bloom Tube-making in England 666	Crane	467
Colvin, Fred H.: Cutting Fractional Screw		It Pays To Keep Informed	Hubbard, Chas. L.:	Motors. Alternating-current, for Railway Work—Ameri-	
Threads 1	143	Machine Shop Equipment. 419	Boiler Bracing 18, 82 Hydraulic Installations 196	can Developments. Wm.	004
Injector Troubles and Re-	227	Mill Type of Construction, The	Index The Cord in the	Baxter, Jr. Motors. Why the Built-in,	304
Compressed Air as an Insula-		Motor. Hitching the 183	Index, The Card, in the Drafting Room 152 Index Plate Drilling Ma-	Failed	256
tor	518	One Way to Keep Up the	Index Plate Drilling Ma- chine, The Le Blond Auto-	Myers, John S. Design of Punch and	
Coolidge, C. E.: Spiral Gears Comments on Drives for	30	Demand	matic 346	Riveter Frames Flexure Simplified	127
Comments on Drives for High Speed Cutting Tools 5	507	tion and Exhibition of	matic		194
Coupling, The Storz System		President Dodge's Address 246 "Standard," Use of the	Installation of the Renold Silent Chain, Notable 456	New Britain Machine Co.,	690
of Pipe	307	"Standard," Use of the Word 417	Silent Chain, Notable 456 Insulator, Compressed Air	Model Plant of the Newport (R. I.) Steam Turbine Station, The	058
Current 4	167	Suggestions That Help 205	as An 518	Turbine Station, The	130 55
Crane, Niles 40-ton Traveling Yard 1	195	Superheated Steam 351 Systematic Presentation of	Jig Making. Frank E.	New Tools of the Month	107
Cranes. The Use of Magnets		Papers 16	Shailor 603	(2)	157
in Connection with. Dr.	003	The Question of Power	Joint For Propeller Shaft,	(5)	277

(6)	Power at the St. Louis Ex-	Single-phase Motor in Eu-	Tool Making. E. R. Mark-
(7) 389 (8) 441	position, The Question of 352 Pratt Institute Courses 527 Press, Large Splice-bar 103 Propoller blade Sheping Me	rope, The. Dr. Alfred Gradenwitz 305	ham.: (1)
(9)	Propeller-blade Shaping Ma-	Smith, M. S.: The Eccentrolinead 535	(3) Reamers (concluded). 289 (4) Counterbores 340
$(11) \dots 617 $ $(12) \dots 679$	Propeller-blade Shaping Ma- chine. Bauer	ing of Aleus 667	(5) Taps
	A Screw	Specifications, Also Tender	(7) Screw Threading Dies 519 (8) Screw Threading Dies
land. James Vose 306 Notes on Design. C. F.	Pumping Station for Phila-	Specifications, Also Tender for Model Engine, How to Draw Up. Geo. P. Pearce 349 Speeds and Feeds. E. R.	(Concluded) 592 (9) Hollow Mills 663
	delphia, Large Fire 361 Punch and Riveter Frames,	Markhain	(9) Hollow Mills 663 Tool Making, A Few Sug-
(1) Machinery Shafting 362 (2) Machinery Shafting 397 Notwithstanding Great Odds 379	Design of, John S. Myers. 127	Spindle Construction. Howard P. Fairfield:	gestions In. Frank E.
OBITUARY.	Reading Room for Employes, A. L. G. Stebbins 93	(1) Modern Methods Dis-	Shailor
Grace, Wm. R., Death of 461 Kempsmith, Frank B., Death	Reamer Clearances. Fred	cussed in Detail 523 (2) 584	ways, French 367 Transmission Problem, An
of	Reid Process for Producing	Spiral Gears. C. E. Coolidge 30 Splice-bar Press, A Large. 103	Transmission Problem, An Interesting Rope 94 Triangle, Adjustable Pro-
McKay, Gordon, Death of 127	Electricity from Fuel 254 Renold Silent Chain, Nota-	Stabel, Joseph M.: Adjustable Die Head and	tractor
Skinner, James N., Death of 226 Thurston, Robt. H., Sudden	ble Installation of 456 Riedler-Stumpf Steam Tur-	Method for Making Threaders for Use in	Drive Freight, Cornell Rid-
Death of	hine. The	Same 207	derhof
Office Building, A Modern. 14 Oil-Testing Apparatus, A	Ridderhof, Corneil: A New Four-Wheel Drive	Measuring External Thread Diameters 248	Turbine Station, The Newport (R. I.) Steam 130 Turbine, The Steam, in a Municipal Station 634 Turbine, Tests on a 4,000 H.
New German Electrical 80	Freight Truck 577 Rifle, The New Springfield,	Straight and Circular Forming Tools 515	Turbine, The Steam, in a
Paints, Value of Fireproof. 509 Patent Law Administration. 372	Adopted by the U. S. Government	Standard Machine Parts.	Turbine, Tests on a 4,000 H.
Pearce, Geo. Pleydell.	Robinson, H.	Designation of 215 Standard Plunger Elevator	Turbine, The Curtis Steam,
How to Draw Up Specifi- cations, Also Tender for	Making of a Shuttle Carrier 470	Co., The Works of the. W. A. Waterman 579	and its Manufacture 1
Model Engines 349 Peat as Fuel 151	Roofs, Machine Shop 70 Rolls for Straightening Pipe 605	Standard Plunger Elevator Co., Details of the 583	Turbine, The Zoelly Steam. 631 Turbine, The Gas
Perkins, Frank C. A Large Vertical Planer. 529	Rope Transmission Problem, An Interesting 94	Steam Engines, Early, A.	Steam 301
Perrigo, Oscar E.		Steam Engines, Early (2) 589	Turbines, Large Westing- house-Parsons 305
Machine Shop Equipment, 11-72-111-171-240-293-375-409	Sargent, W. H. Microphotography 485	ing Engines	Valves, Tools Used in the
Pipe Couplings, The Storz System of	ment of a Modern 184	Steam Turbine at Central Station, Jacksonville, The 634	Manufacture of Globe, J.
System of	Screw Heads 50 Screws 41	Steam Turbine, Tests on a	R. Gordon 427 Variable Speed Motors. Wm.
Plate 228	Secretiveness, A Specious	4,000 H. P 455 Stebbins, L. G.:	Baxter, Jr. (1)
Pipe, Rolls for Straightening	Plea for American Shop 578 Shaft Sinking with the Jump Drill or Trepan, Ex-	A Reading Room for Employes 93	$     \begin{array}{ccccccccccccccccccccccccccccccccc$
Pipe, Wrought 191 Planer, A Large Vertical	Jump Drill or Trepan, Ex- traordinary 464	Steel, High-speed 17 Steel, High-speed, E. R.	(4) 573
Planer, A Large Vertical Frank C. Perkins 529 Planer, A Massive Gear 401	traordinary	Markham	(5) 636 Vose, Jas.:
Planer for High-Speed Steels	Making 486	Walter Brown 534	Notes from Manchester, England 306
with Quick Return of 200 Feet per Minute 587	Jig Making 603 Notes on Die Making 649	Sturtevant Co., Foundry and Pattern Department of the 121	
Planing Machine, A Screw Propeller 61	Shaper, New Design of Fellows Gear 270	Superheated Steam 358	Waterman, W. A.: The Works of the Stand-
Plant, Improvements at the Fore River Ship and En-	Shop of the Betts Mche. Co., The Reconstructed 22	Taper Attachment Gradua- tion, Refinement of 238	ard Plunger Elevator Co. 579 Water Wheel Power Plants,
gine Company's 462	Shop of the Cincinnati	Tapping Machine, A Revers-	Large
Plant of the New Britain Machine Co., Model 639	Shop No. 3, of the Bullock	ible	Blowpipe Metal 345
Plant, The New Worthing- ton	Electric Mfg. Company . 283 Shops of Hooven, Owens &	Test of Turbine Pumps 650 Tests, High-speed Tool Steel 300	Westinghouse-Parsons Turbines, Large
ton	Rentschler Co 231 Shop, R. K. Le Blond Ma-	Thread Diameters, Measuring	What are the New Machine Tools to be? Prof. John
Plunger Elevator Co., Notes	chine Tool Co.'s 403	External. Joseph M. Stabel	E. Sweet 253
from	Shop Secretiveness, A Specious Plea for American. 578	Stabel	E. Sweet
Plunger Elevator Co., Notes from	Shop Secretiveness, A Spe-	Stabel 248	E. Sweet 253
from	chine Tool Co.'s 403 Shop Secretiveness, A Spe- cious Plea for American 578 Shuttle Carrier, Making of	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Es-	E. Sweet
from	chine Tool Co.'s	Stabel 248 Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449	E. Sweet
from	chine Tool Co.'s 403 Shop Secretiveness, A Spe- cious Plea for American 578 Shuttle Carrier, Making of	Stabel 248 Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449	E. Sweet
from	chine Tool Co.'s	Stabel 248 Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449	E. Sweet
from	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels	E. Sweet
from 459 Portable Tools, Electrically- Driven, Dr. Alfred Graden- witz 652  Accident to Diver at Rock- away River Reservoir 473	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247	E. Sweet
from 459 Portable Tools, Electrically- Driven, Dr. Alfred Graden- witz 652  Accident to Diver at Rock- away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon, 307 American Machinery in	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing	E. Sweet
from 459 Portable Tools, Electrically- Driven, Dr. Alfred Graden- witz 652  Accident to Diver at Rock- away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon, 307 American Machinery in France 82 Annealing Cold Rolled Steel 196	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing	E. Sweet
from 459 Portable Tools, Electrically- Driven, Dr. Alfred Graden- witz 652  Accident to Diver at Rock- away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon, 307 American Machinery in France 82 Annealing Cold Rolled Steel 196	Convention, National Maconvention, National M	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing Liberms 156	E. Sweet
from 459 Portable Tools, Electrically-Driven, Dr. Alfred Gradenwitz 652  Accident to Diver at Rock-away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon, 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Png.) School of Tech-	Columns of New York, The Great Cathedral Convention, National Machine Tool Bullders' Association Tool	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing	E. Sweet
from 459 Portable Tools, Electrically- Driven, Dr. Alfred Graden- witz 652  Accident to Diver at Rock- away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Tech- nology 438 Automobile Can Be Driven,	Columns of New York, The Great Cathedral Convention, National Machine Tool Builders' Association in Cincinnati, April 26, 1904 4 367	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing	E. Sweet
from 459 Portable Tools, Electrically-Driven, Dr. Alfred Gradenwitz 652  Accident to Diver at Rock-away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon, 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Png.) School of Tech-	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 549 Hardening Articles in Melted Tin Heating Plant in the Shop.	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon .307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Re-	Columns of New York, The Great Cathedral Machine Tool Builders' Association in Cincinnati, April 26, 1904	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 1549 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 1591 Height of High Interiors, To 1999	E. Sweet
from 459 Portable Tools, Electrically-Driven, Dr. Alfred Graden-witz 652  Accident to Diver at Rock-away River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon, 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Recognified	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 1549 Hardening Articles in Melted Tin 156 Heating Plant in the Shop, Necessity of 156 Helpht of High Interiors, To Find the 159 Hooks, Safety, for Mine Elevators 473	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zisium and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 549 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 549 Height of High Interiors, To Find the 549 Hooks, Safety, for Mine Elevators 473 Hornblower Engine The First Steam Engine in	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela River, The Wabash R. R. 269	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British. for Sawing I-beams 156 Hammer Drill; Expansion Bolt 549 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 51 Hooks, Safety, for Mine Elevators 129 Hornblower Engine The First Steam Engine in America 120	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on	Columns of New York, The Great Cathedral Machine Tool Builders' Association in Cincinnati, April 26, 1904	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 549 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 56 Hooks, Safety, for Mine Elevators 160 Honblower Engine The First Steam Engine in America 120 Inertia, Examples of 250	E. Sweet
Accident to Diver at Rockaway River Reservoir	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American Bridge over Monongahela River, The Wabash R. R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 306 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 151 Heating Plant in the Shop, Necessity of 151 Height of High Interiors, To Find the 151 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 Iron Mountain, Durango's 297 Irrigation, New Plan for 32	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela River, The Wabash R. R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 181	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 396 Hardening Articles in Melted Tin 396 Heating Plant in the Shop, Necessity of 199 Height of High Interiors, To Find the 299 Hooks, Safety, for Mine Elevators 473 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 Inertia, Examp	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Bollers, Defective American 339 Bridge over Monongahela River, The Wabash R. R. 269 Bridge, Strengthening the Brooklyn 336 Bridge, Strengthening the Brooklyn 602 Carborundum and Emery, Distinction in the Abrasive Action of 181 Cast Iron Permanently Ex-	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 649 Hardening Articles in Melted Tin 649 Heating Plant in the Shop, Necessity of 659 Height of High Interiors, To Find the 1100ks, Safety, for Mine Elevators 129 Horbidower Engine The First Steam Engine in America 120 Inertia, Examples of 120 Inertia, Examples of 120 Inertia, Examples of 120 Inertia, Examples of 120 Iron Mountain, Durango's 297 Irrigation, New Plan for 32  Krupp Process. Clalms of Three Steel Companies to the 126	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela River, The Wabash R. R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 181 Cast Iron, Permanently Expanding Not Popular in Bel-	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 549 Hardening Articles in Melted Tin 549 Heating Plant in the Shop, Necessity of 57 Hight of High Interiors, To Find the 57 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 "Invar" for Measuring tapes 250 Iron Mountain, Durango's 297 Irrigation, New Plan for 32 Krupp Process. Claims of Three Steel Companies to the 126 Lamps, Safety Mining 60	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela River, The Wabash R. R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 181 Cast Iron, Permanently Expanding Not Popular in Bel-	chine Tool Co.'s	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 549 Hardening Articles in Melted Tin 549 Heating Plant in the Shop, Necessity of 57 Hight of High Interiors, To Find the 57 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 "Invar" for Measuring tapes 250 Iron Mountain, Durango's 297 Irrigation, New Plan for 32 Krupp Process. Claims of Three Steel Companies to the 126 Lamps, Safety Mining 60	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American Bridge over Monongahela River, The Wabash R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 181 Cast Iron, Permanently Expanding 182 Catalogue System of Advertising Not Popular in Belgium 288 Catalogues, Leaflets as Supplements to 17	chine Tool Co.'s	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 549 Hardening Articles in Melted Tin 549 Heating Plant in the Shop, Necessity of 57 Hight of High Interiors, To Find the 57 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 "Invar" for Measuring tapes 250 Iron Mountain, Durango's 297 Irrigation, New Plan for 32 Krupp Process. Claims of Three Steel Companies to the 126 Lamps, Safety Mining 60	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela River, The Wabash R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 181 Cast Iron, Permanently Expanding 182 Catalogue System of Advertising Not Popular in Belgium 288 Catalogues, Leaflets as Supplements to 17 Cement Construction for Curtain Walls	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 649 Hardening Plant in the Shop, Necessity of 651 Height of High Interiors, To Find the 160 Hooks, Safety, for Mine Elevators 120 Hortia, Examples of 120 "Invar" for Measuring tapes 250 Iron Mountain, Durango's 297 Irrigation, New Plan for 32 Krupp Process. Claims of Three Steel Companies to the 126 Lamps, Safety Mining 60	E. Sweet
Accident to Diver at Rockaway River Reservoir	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 549 Hardening Articles in Melted Tin 640 Heating Plant in the Shop, Necessity of 57 Helght of High Interiors, To Find the 67 Honblower Engine The First Steam Engine in America 120 Inertia. Examples of	E. Sweet
Accident to Diver at Rockaway River Reservoir	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 549 Hardening Articles in Melted Tin 640 Heating Plant in the Shop, Necessity of 57 Helght of High Interiors, To Find the 67 Honblower Engine The First Steam Engine in America 120 Inertia. Examples of	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American 339 Bridge over Monongahela River, The Wabash R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 181 Cast Iron, Permanently Expanding 602 Catalogue System of Advertising Not Popular in Belgium 628 Catalogue System of Advertising Not Popular in Belgium 628 Catalogue System of Advertising Not Popular in Belgium 628 Catalogues, Leaflets as Supplements to 620 Cement Construction for Curtain Walls 621 Cement That Makes Water-Tight Joints 613 Chimney, A Radial Brick 21 Chissel with Inserted Cutter 613 Chuck, Larze Universal 299	chine Tool Co.'s	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass. To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 549 Hardening Articles in Melted Tin 640 Heating Plant in the Shop, Necessity of 57 Helght of High Interiors, To Find the 67 Honblower Engine The First Steam Engine in America 120 Inertia. Examples of	E. Sweet
Accident to Diver at Rockaway River Reservoir	chine Tool Co.'s	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hammer Drill; Expansion Bolt 1306 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 161 Heating Plant in the Shop, Necessity of 171 Height of High Interiors, To 181 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 Inertia, Examples	E. Sweet
Accident to Diver at Rockaway River Reservoir	Columns of New York, The Great Cathedral	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 549 Hardening Articles in Melted Tin 306 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 51 Height of High Interiors, To 190 Hooks, Safety, for Mine Elevators 75 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 120 Inertia, Example	E. Sweet
Accident to Diver at Rockaway River Reservoir	Columns of New York, The Great Cathedral	Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn, in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 199 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of 199 Height of High Interiors, To Find the 299 Hooks, Safety, for Mine Elevators 120 Horn Mountain, Durango's 27 Hrigation, New Plan for 32 Krupp Process, Claims of Three Steel Companies to the 126 Lamps, Safety Mining 80 Lecture on Thermit at Columbia University 127 Let us First Learn to Fly 116 Lock, A Small East Indian 82 Locomotive, Walking 366 Lunch Rooms for Employes 247 Machinery, American, in France 82 Machinery, Exports of 292 Means adopted by Press Agent to Get Free Advertising 1964, and 197 Mechanical Difficulties, Two Ways of Handling 247 Mechanical Difficulties, Two Ways of Handling 247 Mechanical Difficulties, Two Ways of Handling 247 Mechanical Draft, Advantage of, in Central Power Sta-	E. Sweet
Accident to Diver at Rockaway River Reservoir 473 Aerial Navigation 116 Alloys—Zislum and Ziskon 307 American Machinery in France 82 Annealing Cold Rolled Steel 196 Apprentices, Special Classes for, at the Manchester (Eng.) School of Technology 438 Automobile Can Be Driven, Highest Speed at Which 351 Automobile Tires, Heating of 455 Battleships, Our 471 Bells and Whistles, Proper Proportions of, Data Regarding 453 Boilers, Defective American Bridge over Monongahela River, The Wabash R. 269 Bridge, Strengthening the Brooklyn 336 Bronzing Process Used on Cast Iron Hardware 602 Carborundum and Emery, Distinction in the Abrasive Action of 362 Cartorundum and Emery, Distinction in the Abrasive Action of 362 Catalogue System of Advertising Not Popular in Belgium 363 Catalogues, Leaflets as Supplements to 372 Cement Construction for Curtain Walls 363 Catalogues, Leaflets as Supplements to 373 Cement That Makes Water-Tight Joints 385 Chall Handling, Rapid 120 Coal, Regarding the Ex-	Columns of New York, The Great Cathedral	Stabel Threads, Cutting Fractional Screw. Fred H. Colvin. 143 Time for Lathe Work, Estimating. Henry Hess. 449  Comment.  Forgings, High-speed Steels for Reducing 247 Glass, To Turn. in Lathe with Steel Tools 591 Guns, First Wire-wound 527 Hacksaw, A New British, for Sawing I-beams 156 Hammer Drill; Expansion Bolt 306 Hardening Articles in Melted Tin 306 Heating Plant in the Shop, Necessity of Height of High Interiors, To Find the Hooks. Safety, for Mine Elevators 473 Hornblower Engine The First Steam Engine in America 120 Inertia, Examples of 126 Lamps, Safety Mining 80 Lecture on Thermit at Columbia University 127 Let us First Learn to Fly 116 Lock, A Small East Indian 82 Locomotive, Walking 366 Lunch Rooms for Employes 247 Machinery, American, in France 82 Machinery, Exports of 292 Machinery, Exports of 292 Means adopted by Press Agent to Get Free Advertising 127 Mechanical Difficulties, Two Ways of Handling 247 Mechanical Draft, Advantage of, in Central Power Sta- filons 307	E. Sweet

Sewing Machine Invented in 1814, A	Tests of Boiler Joints with Nickel Steel Rivets, Re- sults of	Turbine, One Valuable Feature of the Steam	Weighing Bridge for Moving Trains
	Engineerin	g Review.	
Acetylene Gas Absorbed in Acetone for Safe Transportation	Cutters of Complicated Shape, High-speed Steels and Their Use for 36 Cylindrical Grinding 140  Darlington Hotel, Collapse of Framework 422 Death of Jas. P. Lee 420 Decimal Classification, Dewey 595 De Laval Steam Turbine, The 599 Depth of Liquids in Tanks, etc. The "Depthometer," A Device for Measuring the 139 Depthometer, The : for Measuring Depth of Liquids in Tanks, etc 139 Depthometer, The if or Measuring Depth of Liquids in Tanks, etc 139 Depthometer, The if or Measuring Depth of Liquids in Tanks, etc 139 Depthometer, The if or Measuring Depth of Liquids in Tanks, etc 139 Depthometer, The if or Measuring Depth of Liquids in Tanks, etc 139 Depthometer, The if or Measuring Depth of Liquids in Tanks, etc 139 Depthometer, The if or Measuring Depth of Classifications 595 Dies for Drop Forgings 139 Disks, Experiments to Determine the Air Friction of 201 Drop Forging 34 Electric Locomotives, Shocks from 34 Electricity for Separating Oil From Water, Use of 537 Electricity in Manufacturing Plates 205 Electro-magnets for lifting Plates 205 Electro-magnets for lifting Plates 259 Engine, Multiple Expansion Steam 475 Engine Newcomen, at the Ashton Vale Iron Works 261 Engine, Novel Jacketed 89 Engines and Pumps Without Glands 88 Envelopes, Machine for Opening 421 Ericsson, The Man 91 Farmers Provided with Power by an Illinois Ry. Company 308 Ferry, Suspended Car 368 Fille-cutting Machine 91 Fillter for Removing Cylinder Oil from the Condensation	Heat Gage, The Morse	Notebook, Keeping an Engineer's Nut Lock, A New 634 Oil Engine in Which Oil is Vaporized and Ignited Without Use of Any Ex- ternal Source of Heat 135 Oil Successfully Removed from the Condensation of Engines by the Rankine Cartridge Filter 305 Oil Tank Car, Bettendorf 505 Oil Tank Car, Bettendorf 505 Oil Thefts Stopped in India 420 Packing Device, Locomotive Throttle-stem 130 Packing Device, Locomotive Throttle-stem 130 Palexing Device, Locomotive Testalling Off in Number of Good. 650 Peat as Fuel in Germany 440 Patents? Falling Off in Number of Good. 650 Peat as Fuel in Germany 440 Patenser of Frozen Water 421 Pateroleum for Road Purposes 88 Pipes by Electricity, Thawing of Frozen Water 421 Pipe, The Manufacture of 540 Piping in Steam Plants, Danger of Defective 421 Piston Ring Hammer 641 Plant at the Louislana Purchase Exposition, Locomotive Testing 131 Platinum 131 Patinum 132 Platinum 134 Patinum 135 Patinum 136 Power Plant for N. Y. Terminal of P. R. R. 131 Pressure of Granular Substances on the Walls of Deep Bins 140 Pulley, Balancing a Loose 132 Pulley, Balancing a Loose 132 Pumps, Double-acting 134
Boiler Explosion, Water tube 368 Borings Lose Their Sulphur Contents, Pig and Cast Iron	of Engines. The Rankine Cartridge	Furnace 90 Loads, Permissible Foundation 199 Locomotives, Consular Report Recommending Superheated Steam 595	Pump, High-Pressure Multi- Stage Turbine
Calcium Carbide in Life Saving Apparatus, Use of	Beams Ready for Use 200 Floors, Machine Shop 310 Flywheels on Board Ship, Gyroscopic Effects of 478 Flywheel Gyrostatic Effects and Broken Crankshafts 424 Formula, for Determining the Specific Heat of Superheated Steam 537 Foundations Permissible Loads for 199 Freight Run, Record 200 French Law as Preventing Contracts 200 Friction Between Wood and and Iron 87	Locomotive, Mallet Articulated Type, for the B. & O. Locomotive Tests in Germany, High Speed Steam 597 Locomotive Worked Its Way on the Ohio River, How a. 257 Locomotives, Electric 257 Louisiana Purchase Exposition, Locomotive Testing Plant at the 424 Machinery for Export, Packing of 424 Machinist Must be a Specialist 200 Manganese Steel, Hadfield's 656	Rallroad, The Most Northerly in the World
Combustion Effected by Distilling	Gang Planing Tool	Measuring Areas, New Device for	Rings. Elasticity of Cast Iron Piston Rivets instead of Bolts in Locomotives, The Use of 258 Rolling Process. Continuous. 368 Rolling Process. Continuous. 369 Ropes, Round Taper 309 Saw. the Band, an English Invention 300 Saw. The Largest Circular in the World 300 Saw. The Largest Circular in the World 300 Saw. The Largest Circular in the World 300 Saw. The Largest Circular Saw. The Largest Circular Saw. The Largest Circular in the World 300 Saw. The Largest Circular in the Salum 300 Saw. The Largest Circular in the World 300 Saw. The James Circular in the World 300 Saw. The James Circular in the World 300 Saw. 300 Sa

Sleeping Cars for Electric Lines	Superheated Steam for Steam Engines	Trade Marks, Proprietary Rights in	Turbine, The Parsons Steam 601 Turbine, The Rateau Steam. 137 Turbines Compared, Steam. 141 Turbines for the New Scout Ships of U. S. Navy, Steam
	Items of Mech	anical Interest.	
Alloy—"Wood's Metal"	Die Work on a Large Scale as Practiced at the Heslop Seamless Steel Boat Works, England	Marine Engine Model, Triple Expansion	Surface Plate with V-groove for Laying Out Work
	Letters upon Pr	actical Subjects.	
Air Drill in Remote Shops, The Value of	Chuck for End Mills	Flywheels, Chuck and Milling Fixture for Gas Engine. 607 Forming Tool, making a Concave. 213 Formulas, Bevel Gear. 148 Formulas, Re Bevel Gear. 380 Friction, On the Subject of. 48 Gege, Shailor's Multiplying. 606 Gear Cutter, A German Spiral 149 Gear-cutting Machines, 270 Gear Formulas, Re Bevel. 380 Gear Teeth, The Strength of 98 Gear Teeth, The Strength of 98 Gear Teeth, The Strength of 98 Gear Formulas, Re Bevel. 380 Gear Teeth, The Strength of 613 Gears, Figuring a Pair of Spiral 276 Grinder for Controller Contact 276 Grinder for Controller Contact 358 Hangers and Supports for Use with Turret Lathes, Adjustable 145 Hardening Work in Part. 671 Holder, A Handy Boring Tool 272 Indexing, A Simple Case of Compound 433 Jig, A Time-saving Drill 213 Jig and Counterbore, A Drill 314 Jig for Boring Rough Castings Another 677 Jig Making, Accurate 550 Jig if Superheated 582 Jignil 507 J	The Value of the Cooper-Hewitt
Rough	Brawing Cabinet for Home Use, A Handy         385           Eternal Question, The         434           Eternal Ouestion, The         609           Face Milling         47           Facing Studs for Lathe Chuck         678           Facing with an Upright Drill, Large         209	Knurling, How a Bastard File was Used for	Punch and Die, Machining A Difficult

Rises, Chords and Radii of Circular Arcs from the Coordinates of a Curve, The Determination of	Spiral Gear Cutter, A German	Superheated Steam, Pipe Joints for	Tools for a Manufacturing Operation, Set of
	Shop	Kinks.	
Addition and Subtraction Chart 104 Apron, An Improved Form of Planer 218 Arbor for Turning and Grinding Boring Cutters 437  Babbitted Boxes, Removing Shafts from 156 Babbitt Sockets for Ratchet Drills Bearings, Method of Making Rings for Self-oiling 386 Blueprint Washing Tray, Vertical 387 Bushings, Dimensions for Standard Jig 438  Calipers, Home-made Shoulder 104 Calipers, Some Makeshifts with 164 Calipers, Home-made Shoulder 164 Calipers, Home-made Shoulde	Counterboring Holes for Pattern Work	Hardened Steel, Drilling 559 nexagons, Tool for Laying Out	Scraper for Boxes, Handy. 386 Screw Heads, Jig for Slotting
Clamping Flat Work, A Device for	Hack Saw, Cutting Slots with a	ings, Method of Making 386 Rocker Arm, Repair of 386	Vise Jaws for Planing Keyways, Special 218
14. Annealing Tools Made of the New Process Steels	9. Gear Pattern, Cutting 106 27. Governor Balls, Effect of Changing Weight of 439 14. Hardening Tools Made of the New Process Steels. 269 12. Harvey and Krupp Processes for Hardening Steel Plate 219 24. Heat of Oil, Specific. 439 41. Heat, Soldering Without 561 7. Horse Power of Electric Motor 106 Removing Scales from Boiler Plates, Use of 439 25. Link Block Length, To Equalize the Throw of. 439 44. (1) Milling Cutters, How to Make Formed 561 3. Milling Slots on a Taper Reamer 54 29. Momentum and Velocity of Flywheels 439 31. Nomenclature for Distinguishing Carbon from	Steel	35. Solder or Composition for Automatic Fire Sprink-lers
	Data S	Sheets.	
SEPTEMBER: (1) Constants for Finding Diameter of Bottom of Thread.  (2) Comparison of Twist Drill (Morse) and Drill Rod (Crescent or Kidd-Stubbs) Number Sizes.  (3) Morse Standard Tapers.  (4) Brown & Sharpe Standard Tapers.  (4) Brown & Sharpe Standard Tapers.  OCTOBER: (1) Diametral Pitches for 15-degree Involute and Cycloidal Cast-iron Gear Teeth per Inch width of face for Continuous Service in One Direction.  (2) Diametral Pitches for 15-degree Involute and Cycloidal Cast-iron Gear Teeth, per Inch Width of Face, for Continuous Service in One Direction. (Continued.)  (3) Formulas for Ball and Roller Bearings.  (4) Formulas for Ball and Roller Bearings. (Continued.)  NOVEMBER: (1) Diagram of Torsional Shearing Strength of Round Shafts for Different Fiber Strains per Square Inch.  (2) Diagram of Transverse Strength of Round Shafts for	Different Fiber Strains per Square Inch.  (3) Diagram of Strength of Round Shafts for Combined Twisting and Bending Moments.  (4) Diagram of Round Shafts. for Finding Diameters at Different Fiber Strains when Diameter for Fiber Strain of 7.500 Pounds has been Found from Table 3.  DECEMBER: (1) Diagram for Designing Beams.  (2) Diagrams for Designing Beams.  (3) Table of Sectional Moduli and Weights per Foot of Beams of Various Sections.  (4) Table of Sectional Moduli. (Continued.)  JANUARY: (1) Standard Upset. Cottered and Tee Bolt Ends.  (2) Dimensions for Brass Handwheels (U. S. Navy Standard).  (3) Standard Babbitted Bearings.  (4) Standard V-strips. Standard Male and Female Brass Flanges for 250 pounds Pressure.  FEBRUARY: (1) Weight of Rolled Sheet Metals. Weight in	Pounds Avoirdupols per Square Foot.  (2) Approximate Weight per Inch of Face for Cast-Iron Gears.  (3) Weights and Areas of Cold Rolled Steel Shafting.  (4) Weight of a Superficial Foot of Cast Iron, Weights of Nuts and Bolt Heads in Pounds; Specific Gravity and Weight of Metals.  MARCH: (1) Diagram of Journal Friction Showing Resistance at Pitch Diameter of Wheel in Terms of Load on the Journal.  (2) Diagram of Chain Friction Showing Resistance Due to One Bend of Chain.  (3) Standard Drum Scores.  (4) Standard Soft Steel Rope Sockets with Pin.  APRIL: (1) Contents MACHINERY Data Sheets (Cont.).  (3) Comparisons of Money Standards.  (4) Logarithms of Convenient Constants, Composition of	Bronzes (Navy Department.) MAY: (1) Tap Drills for "V" Threads. (2) Tap Drills for "V" Threads. (Continued.) (3) Table of Angles for Head- stock of Milling Machine, when Cutting End Teeth in Mills, etc. (4) Diagram of Diameters and Speeds.  JUNE: (1) Chain End Link and Narrow Shackle. (2) Proportions of Keys. (3) Crane Chain. Table for Eye Bolts. (4) Proportions of Hooks.  JULY. (1) Standard Boller Rivets. (2) Length (Under Head) of Rivets. (3) Standard Round Slotted Nuts. (4) Inches to Decimals of a Foot.  August. (1) Size of Wire, Drills or Sheets. (2) Size of Wire, Drills or Sheets. (3) Size of Wire, Drills or Sheets. (4) Useful Factors.

